

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2023

Submitted Date:

07/05/2023

Document Number:

694100110

FIELD INSPECTION FORM

 Loc ID 427430 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 200642

Name of Operator: CIVITAS RESOURCES INC

Address: 555 17TH STREET SUITE 3500

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|-----------------------------------|-----------------|
| Antonioli, Philip | 720-345-4603 | pantonioli@civiresources.com | |
| , | | Inspections@civiresources.com | |
| , | | COGCCInspections@extractionog.com | All Inspections |

General Comment:

This is an environmental inspection for Location/Facility ID: 427430 Lamb 42-15 Facility. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: No signs on site. Site has been decommissioned. All equipment has been removed. Site seems to be ready for reclamation.

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment: Oily substance was on location. Could be a small diesel or gasoline spill.

Multiple Spills and Releases?

Fencing/:

| Type | | | |
|--------------------|---|-------|-------------------|
| | | | |
| Comment: | Open excavation on location. Approximately 10ft x 12ft x 5ft. | | |
| Corrective Action: | Fill open excavation. Install safety fencing until excavation can be filled in. Comply with the fencing requirements per the 1002a rules."For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e."" For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS"" | Date: | <u>07/20/2023</u> |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Oily substance was on location. Could be a small diesel or gasoline spill.

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e."" For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""" Date: 07/12/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694100111 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169928 |