

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE
Location #312658
Date: 7/3/2023



NW Corner of Location – Photo #04981



NE Corner of Location – Photo #04982

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE
Location #312658
Date: 7/3/2023



SE Corner of Location – Photo #04983



SW Corner of Location – Photo #04984

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE
Location #312658
Date: 7/3/2023



Wellhead/Weeds – Photo #04988



Separator/Weeds – Photo #04995

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE
Location #312658
Date: 7/3/2023



**Tank Battery/Insufficient Capacity & Permeability of
Secondary Containment – Photo #04992**



Anchor Not Properly Marked – Photo #04987

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE
Location #312658
Date: 7/3/2023



Stained Soil Near Pump Jack – Photo #04991



Unprotected Spoil Pile – Photo #04985

VISION ENERGY LLC, SULFUR GULCH 9-98-1-69S98W/1SWNE

Location #312658

Date: 7/3/2023



Unprotected Spoil Pile – Photo #04986