

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2023

Submitted Date:

07/05/2023

Document Number:

708300655

## FIELD INSPECTION FORM

 Loc ID: 312511  
 Inspector Name: Morris, Matthew  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 10770  
 Name of Operator: VISION ENERGY LLC  
 Address: P O BOX 370  
 City: IGNACIO State: CO Zip: 81137
**Findings:**

- 10 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	
Byers, Jim		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221818	WELL	TA	01/01/2021	GW	077-08420	FEDERAL 35-2	TA

**General Comment:**[COGCC Inspection Report Summary](#)

On 7/3/2023 at approximately 13:20, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, FEDERAL-68S98W/35SEW at Location ID #312511 in Mesa County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Weeds present near wellhead and in pits
- 2) Debris on location
- 3) Unused gas meter run on location
- 4) Wellhead sign not posted
- 5) Bradenhead inaccessible or not visible
- 6) No permit on file for two pits on location
- 7) No MIT on record for TA well

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road to location crosses an unprotected creek bed with no stormwater BMPs in place.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead sign not posted.		
Corrective Action:	Post wellhead sign to comply with Rule 605.d.	Date:	08/04/2023

<b>Emergency Contact Number:</b>			
Comment:	911/(970) 858-8550		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run on location.		
Corrective Action:	Remove unused equipment from locatino to comply with Rule 606.	Date:	08/04/2023
Type	WEEDS		
Comment:	Weeds present near wellhead and pits		
Corrective Action:	Remove weeds to comply with Rule 606.	Date:	07/12/2023
Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris to comply with Rule 606.	Date:	07/12/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	07/15/2023
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 221818 Type: WELL API Number: 077-08420 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced prior to 1999. No MIT on record.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within the 30 day CA time, the well must be plugged within 3 months per Rule 417 and 210.

Date: 08/04/2023

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Inadequate

Comment: Two pits on location with no permit on record for either of them.

Corrective Action:

Submit an eForm 15 Pit Report to update records with current information to comply with rule 908.

Date: 07/20/2023

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300656	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170324</a>