

API 05-075-05229



00209042

OGCC FORM 4  
Rev. 1/78

**STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES**

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

FOR OFFICE USE			
ET	FE	UC	SE

5. LEASE DESIGNATION &amp; SERIAL NO.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Brandly Oilman Consultants, Inc.		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 1333 West 120th Ave., #306, Westminster, CO 80234		8. FARM OR LEASE NAME Dune Ridge	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface CS 1/2 N 1/2 32-7N-52W At proposed prod. zone 2640 FWL & 1980 FNL		9. WELL NO. 11	
14. PERMIT NO. Unable to locate		15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
		12. COUNTY Logan	
		13. STATE COLO.	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL,

CHANGE PLANS

(Other)

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work As soon as possible

\* Must be accompanied by a cement verification report.

To plug and abandon the above well. Shoot off and pull casing at about 3800 feet. Cover perforations with sand. Set 5 sx. plug on sand. Set 20 sx. plug in and out of surface casing. Set 5 sx. plug at surface. Cut off and weld cap on surface. Donnelly Casing Pulling to do the work.

**RECEIVED**

MAY 05 1989

COLO. OIL &amp; GAS CONS. COMM.

19. I hereby certify that the foregoing is true and correct

PRINT Larry BrandlySIGNED Larry Brandly TITLE President DATE April 24, 1989

(This space for Federal or State office use)

APPROVED BY Stephen Roth  
CONDITIONS OF APPROVAL, IF ANY:TITLE Petro-Eng. CDATE 5/15/89