

**Inspection Photos**  
**Location Name: Ocoma 31-18**  
**API # 05-123-14803**



**Well**



**Mechanical Conditions “leaking packing”**