

STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES



00209005

FOR OFFICE USE

ET	FE	UC	SE
DEPT	INVEST	PLANNING	REGISTRY

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION & SERIAL NO.

6. IF INDIAN ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

12. COUNTY

13. STATE

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

Brandly Oilman Consultants, Inc.

3. ADDRESS OF OPERATOR

1333 W. 120th Ave., #306, Westminster, CO 80230

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

NW/SE Sec. 32-7N-52W

At proposed prod. zone

Same

14. PERMIT NO.

Unable to locate.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

LOGAN

COLO.

RECEIVED

NOV 13 1989

COLO. OIL & GAS CONS. COMM.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work As soon as possible.

\* Must be accompanied by a cement verification report.

To plug and abandon the above well. Shoot off and pull casing <sup>25</sup> at about 3800 feet. Cover perforations with sand. Set 5 sx. plug on sand. Set 20<sup>25</sup> sx. plug in and out of surface casing. Set 5 sx. plug at surface. Cut off plug and weld cap on surface. Donnelly Casing Pulling to do the work.

or: Cover perforations with sand. Set 5 sx. plug on sand. Set 15 sx. plug @ surface. Cut off and weld cap on surface.

RECEIVED

MAY 05 1989

COLO. OIL & GAS CONS. COMM.

19. I hereby certify that the foregoing is true and correct

PRINT Larry Brandly

SIGNED Larry Brandly TITLE President

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE SUPR. PETROLEUM ENGINEER DATE 5/15/89

CONDITIONS OF APPROVAL, IF ANY: