

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 1 – Pumping Unit – WEEDS



Photo 2 – Pumping Unit – WEEDS



Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 3 – Gas Engine – WEEDS



Photo 4 – Wellhead – WEEDS

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 5 – Wellhead – WEEDS



Photo 6 – ECD and Separator – WEEDS

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699




Photo 7 – Unmarked Riser at ECD – WEEDS



Photo 8 – Flare– WEEDS

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 9 – WEEDS



Photo 10 – WEEDS

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 11 – Tank Battery Sign – WEEDS



Photo 12 – Tumbleweeds

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 13 – Tank Battery



Photo 14 – Inadequate Capacity Label

Inspection Photos
Location Name: Washburn GX15-62HN
Location ID: 428699



Photo 15 – Weeds



Photo 16 – Tank Battery