

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/05/2023

Submitted Date:

07/06/2023

Document Number:

702501599

**FIELD INSPECTION FORM**

Loc ID 334600 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282717	WELL	PR	05/27/2006	GW	045-11806	BOSELY SG 41-27	PR
282718	WELL	PR	05/28/2006	GW	045-11805	BOSELY SG 341-27	PR
282719	WELL	PR	05/29/2006	GW	045-11804	BOSELY SG 441-27	PR
422051	WELL	PR	01/11/2012	GW	045-20485	Bosely SG 331-27	PR
422052	WELL	PR	01/11/2012	GW	045-20486	Bosely SG 431-27	PR
422054	WELL	PR	01/12/2012	GW	045-20488	Williams SG 531-27	PR
422055	WELL	PR	01/05/2012	GW	045-20489	Bosely SG 31-27	PR

**General Comment:**

[COGCC Inspection Report Summary](#)

On Monday, 7/5/2023, Inspector Kirby Burchett, conducted a follow up field inspection at TEP Rocky Mountain LLC on the Bosely SG 41-27 Pad, Location #334600, in Garfield County, Colorado. Lock combination has been changed on the gate. Had to call Operator for the combination to gain access.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District Wildlife Management Area with Black Bear, High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

All Corrective Actions from Inspection #702501031 on 3/27/23 have not been resolved. Gas meter calibration not visibly displayed.

While there during normal operations the following compliance issue was observed:

1. Gas meter calibration not visibly displayed.

A follow up on this site inspection will be conducted to ensure compliance issue has been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Fence panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Fence panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Fence panels		
Corrective Action:			Date:

**Equipment:**

Type: Horizontal Heated Separator	# 7		corrective date
Comment:	1 Quad unit, 1 Double unit, 1 Single unit		
Corrective Action:			Date:
Type: Plunger Lift	# 7		

Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Automation installed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:	Inside separators. Gas meter calibration not visibly displayed.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	07/16/2023
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		
Comment:	Loadline and tank valves capped or plugged.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		
Comment:	Loadline and tank valves capped or plugged.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	282717	Type:	WELL	API Number:	045-11806	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	282718	Type:	WELL	API Number:	045-11805	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	282719	Type:	WELL	API Number:	045-11804	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	422051	Type:	WELL	API Number:	045-20485	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	422052	Type:	WELL	API Number:	045-20486	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	422054	Type:	WELL	API Number:	045-20488	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		
Facility ID:	422055	Type:	WELL	API Number:	045-20489	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
Compaction						
Ditches						
		Culverts				
		Gravel				
		Compaction				
Gravel						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501604	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6171634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6171634</a>