

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2023

Submitted Date:

07/06/2023

Document Number:

708900935

**FIELD INSPECTION FORM**Loc ID 335295 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211334	WELL	PR	09/07/1997	GW	045-07094	RMV 65-20	PR
260690	WELL	PR	06/10/2002	GW	045-07901	CLOUGH RWF 534-20	PR

**General Comment:****CECMC Inspection Report Summary**

On 07/06/2023 at approximately 09:13 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location # 335295 in Garfield County Colorado.

Please refer to Inspection 708900422 conducted on 05/05/2023, previous corrective action has been completed.

Location is within High Priority/Density Habitat areas &amp; within close proximity to Bald Eagle Nest &amp; Roost Sites.

Location is approximately 168 yards from a drainage/creek that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Remote location - 2 wells associated with this location are on another pad, CLOUGH RWF 434-20 pad, location # 335342

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Marked			
Corrective Action:				Date:
Type: Gas Meter Run	# 4			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Cataflow			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient		
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Centralized containment				

Corrective Action:		Date:		
<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity) 80 bbl				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	
Comment:				
Corrective Action:		Date:		
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:		Date:		
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:		Date:		

Inspected Facilities									
Facility ID:	211334	Type:	WELL	API Number:	045-07094	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260690	Type:	WELL	API Number:	045-07901	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Compaction						Small areas of light compaction
		Culverts				
Gravel						Sparse in some areas
		Ditches				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Split pad/Remote location - 2 wells associated with this location are on another pad, CLOUGH RWF 434-20 pad, location # 335342	smelserw	07/06/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900936	Inspection 708900935 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6172212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6172212</a>
708900937	Inspection 708900935 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6172213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6172213</a>