

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204387

FIELD INSPECTION FORMLoc ID 324823 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212935	WELL	PR	05/01/2021	GW	061-06296	FRAZEE 1-6	RI

General Comment:On 6/29/2023, Ryan Costa conducted a location inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	There is oily fluid and sludge that is overtopping the containment where barrels are stored at the punmpjack. Operator was notified the day of inspection for immediate clean up.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906.		Date: 06/29/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Tank			
Comment:	There is oily sludge that has overtopped the tank and berm. Operator was notified the day of inspection for immediate clean up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 06/29/2023

In Containment: No ☐Comment: ☐ Multiple Spills and Releases?

Fencing/:				
Type	TANK BATTERY			
Comment:	The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Corrective action is the day of inspection and the location will remain out of compliance until completed.			
Corrective Action:	Comply with the fencing requirements per the 1002a rules			Date: 06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1		Open Top		,	
Comment:	The netting on the tank is torn and needs to be repaired. Operator was notified the day of inspection for immediate repair.					
Corrective Action:	Install or repair wildlife protection equipment.				Date: 06/29/2023	

Paint

Condition	<input type="text"/>				
Other (Content)	<input type="text"/>				
Other (Capacity)	<input type="text"/>				
Other (Type)	<input type="text"/>				

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Inadequate		Inadequate	
Comment:	The berm at the open top tank is inadequate to contain a spill. There are animal boroughs at the earthen berm that need to be repaired. Corrective action is the day of inspection and the location will remain out of compliance until completed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 06/29/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403451245	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166802
690204388	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166779