

Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The cattleguard has been removed and the road regraded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023

Inspection Photos



Photo 2. Facing west toward the access road which has been reclaimed. There is a 1 strand electric fence around the reclaimed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023

Inspection Photos



Photo 3. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023

Inspection Photos



Photo 4. There is desirable and undesirable vegetation growing throughout the reclaimed area. It appears vegetation has been mowed for weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023

Inspection Photos



Photo 5. West side of the location facing west. There is signs of vehicle use from the west entering the location. This is not the permitted access and vehicles must stay off of adjacent land.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 7/6/2023