

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2023

Submitted Date:

07/07/2023

Document Number:

705000359

FIELD INSPECTION FORM

Loc ID 333013 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271688	WELL	SI	02/01/2022	OW	123-22101	WILSON 7-17	PA

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 271688 Type: WELL API Number: 123-22101 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Wilson 7-17) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403339073 received 03/07/2023. OLF WH flowline abandonment/ removal work appears to be completed; no flowline risers observed at WH excavation. COGCC form 42 flowline abandonment completed notice doc #403437809 received 06/19/2023. Fenced excavations also observed at facility/ battery; decommissioning work is in progress. Removal of on location dump and process flowlines at facility/ battery is in progress. Excavation/ remediation work (per form 27) is in progress.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403448691 received on 06/30/2023: On June 28, 2023, historically impacted soil was discovered following flowline removal operations at the Wilson 7-17 wellhead location. Excavation and assessment activities are ongoing. Historically impacted soils were discovered following flowline removal operations. Site infrastructure has been removed and will not be replaced.	maclarej	07/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000360	Fenced bellhole excavation; OLF removal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173339
705000361	Facility decommissioning; fenced excavations	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173340