

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2023

Submitted Date:

07/07/2023

Document Number:

702501610

FIELD INSPECTION FORM

Loc ID 335306 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259331	WELL	PR	02/19/2001	GW	045-07713	UNOCAL GM 14-27	PR
259371	WELL	PR	02/23/2001	GW	045-07719	UNOCAL GM 209-27	PR
273300	WELL	PR	08/01/2020	GW	045-10236	WILLIAMS GM 414-27	PR
273301	WELL	PR	01/19/2005	GW	045-10235	WILLIAMS GM 514-27	PR

General Comment:**COGCC Inspection Report Summary**

On Friday, 7/8/23, Inspector Kirby Burchett, conducted a follow up field inspection at TEP Rocky Mountain LLC on the GM 14-27 pad, Location #335306, in Garfield County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District Wildlife Management Area with Black Bear, High Priority, NSO, and Density Habitat regulations.

Gate combination had been changed. Called Operator number with the answering service picking up the call. Got a response back with the correct combination 56 minutes later.

Any Corrective Actions from previous Inspections are still applicable.

Corrective Action for no visible display of gas meter inspection from Inspection #702501036 on 3/28/23 has not been resolved.

While there during normal operations the following compliance issues were observed:

1. Debris.
2. Surface casing valves left open.
3. Gas meter calibration not visibly displayed.
4. Stormwater BMPs insufficient.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-285-9377 / 911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris		
Corrective Action:	The storage of all supplies not necessary for use on an Oil and Gas Locations is prohibited.	Date:	07/15/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Fence panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Fence panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Fence panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:	2 Double units		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	Inside separator units. No visible display of calibration.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 07/18/2023
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:	Open end loadline addressed on Inspection #702501609				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined			
Corrective Action:				Date:

Venting:

Yes/No	YES
Comment:	Bradenhead valves left open on the GM 209-27 and GM 414-27 wells
Corrective Action:	Shut in immediately. Bradenhead pressure is to be monitored monthly and reported as required. Venting is not allowed without special approval from engineering.
Date:	07/10/2023

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	259331	Type:	WELL	API Number:	045-07713	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	259371	Type:	WELL	API Number:	045-07719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	273300	Type:	WELL	API Number:	045-10236	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	273301	Type:	WELL	API Number:	045-10235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						
Berms						
		Gravel				
		Ditches				
Waddles	Fail					
Sediment Traps						
		Culverts				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 07/18/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501614	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173519