

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2023

Submitted Date:

07/08/2023

Document Number:

708900949**FIELD INSPECTION FORM**Loc ID: 324090 Inspector Name: Smelser, Wayne On-Site Inspection: ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256709	WELL	PR	01/20/2000	GW	045-07487	CLOUGH RMV 92-29	PR

**General Comment:****CECMC Inspection Report Summary**

On 07/07/2023 at approximately 10:48 hours, I, Compliance Specialist, Wayne Smelser  
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 pad.  
Location # 324090 in Garfield County Colorado.

Please refer to Inspection 708900235 conducted on 04/05/2023, previous corrective actions have been completed.

Location is within High Priority/Density habitat areas & within close proximity to NSO Habitat area & Bald Eagle Nest & Roost sites.

Location is approximately 265 yards from a drainage that contributes to the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Open ended load line with a CA date of 07/15/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Remote location/split pad - 2 wells associated with this location are on another pad, CLOUGH RWF 421-29 pad location # 335371

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 3			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Open ended load line			
Corrective Action:	All load lines will be capped or plugged			Date: 07/15/2023
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Marked			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient			
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,

Comment:	Centralized containment					
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	80 bbl					
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent				
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	256709	Type:	WELL	API Number:	045-07487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				Sparse
Gravel						Sparse in some areas
		Compaction				Small areas of light compaction
Compaction						Small areas of light compaction

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	07/08/2023
Remote location/split pad - 2 wells associated with this location are on another pad, CLOUGH RWF 421-29 pad location # 335371		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900950	Inspection 708900949 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173664">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173664</a>
708900951	Inspection 708900949 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173665">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173665</a>