

# Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/6/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-05145 - Date: 7/6/2023

## Inspection Photos



**Photo 1.** Facing south toward the access road. The access road has been recontoured and reclaimed. There is some desirable and undesirable growing along the reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 7/6/2023

## Inspection Photos



**Photo 2.** Facing south along the access road near the location. The electric transmission line has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 7/6/2023



## Inspection Photos



**Photo 3.** Facing south toward the location which has been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 7/6/2023

## Inspection Photos



**Photo 4.** View of ground cover shows some desirable vegetation establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 7/6/2023