

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2023

Submitted Date:

07/11/2023

Document Number:

712700381

FIELD INSPECTION FORM

Loc ID 333341 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10755
Name of Operator: MORNINGSTAR OPERATING LLC
Address: 400 W 7TH ST
City: FORT WORTH State: TX Zip: 76102

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|------------------------------------|
| Kittinger, Eric | | ekittinger@mspartners.com | All SW Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|--|
| Type | WEEDS | | |
| Comment: | Weedy species growing sporadically across the well location and around the wellheads and separators. See Photo #3. | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No _____

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | 6-ft. chainlink. | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Pipe and hog wire. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | corrective date |
|---------------------------------|-----|-------|-----------------|
| Type: Vertical Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |

| | | | |
|---------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 2 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | 8" line | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Gathering Line | # 1 | | |
| Comment: | 6" line, buried valve can. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 3 | | |
| Comment: | 3" line from separator to meterhouse. Calibrated within one year. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 3 | | |
| Comment: | 2" line from wellhead to separator. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 2 | 400 BBLs | STEEL AST | | 37.002930,-107.434120 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Wells Served By Facilities Above

AirsID

| |
|------------|
| API Number |
| 007-06219 |
| 007-06231 |

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|-------|-------|
| Yes/No | NO | Date: | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|-------|-------|
| Type | | Date: | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--------------------------------|
| Berms | Pass | Ditches | Pass | Material Handling And Spill Prevention | Pass | Containers within containment. |
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 712700386 | Well Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176142 |