

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/12/2023

Submitted Date:

07/12/2023

Document Number:

699106924

**FIELD INSPECTION FORM**

Loc ID 332212 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joe		joeobenergy@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332212	LOCATION	AC			-	SOUTH LOST CREEK-63N62W 28SWSW	AC

**General Comment:**

This is an inspection on the Tank Battery

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Pit placard is weathered and needs replaced. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 08/25/2023
Type	TANK LABELS/PLACARDS		
Comment:	Unreadable Capacity for pit. See attached phot		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 08/25/2023

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around the pit and by crude oil tank needs to be removed. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 08/25/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment next to the gas meter run, needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606		Date: 08/25/2023
Type	WEEDS		
Comment:	Weeds grown in multiple spots need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606		Date: 08/25/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:			Date:

**Equipment:**

Type: Pig Station	# 1		corrective date
-------------------	-----	--	-----------------

Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.191900,-104.336900
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are starting to show being weathered and will need to be repaired in the near future.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:



**Inspected Facilities**Facility ID: 332212 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: ac

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 7/12/23 at approximately 1030hrs I, Inspector Adam Burns, Conducted an on-site inspection at South Lost Creek-63N62W 28SWSW Tank Battery of O'Brien Energy Resources Corp.</p> <p>Location ID: 332212 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pit placard is weathered and needs replaced. Install sign to comply with Rule 605.g. With a Corrective Action date of 8/25/23</p> <p>Unreadable Capacity for pit. Install sign to comply with Rule 605.g. With a Corrective Action date of 8/25/23</p> <p>Unused equipment next to the gas meter run, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 8/25/23</p> <p>Weeds grown in multiple spots need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 8/25/23</p> <p>Stained soil around the pit and by crude oil tank needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 7/21/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	07/12/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106925	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6178426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6178426</a>