

Inspection Photos

API: 043-06124

Operator: JAVERNICK OIL

Inspection Date: 7/13/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 1. Facing south along the access road. There is erosion that occurred at the drainage crossing from recent storm event. The road has been washed out and needs to be repaired and BMP's need to be installed at the drainage crossing such as an adequately sized culvert. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 2. There is erosion along the road side that needs to be repaired and stabilized with BMP's. Red arrow points to 4.5' shovel for scale. There is a long stretch from this point further along the road with no culverts to divert stormwater off the road. Additional BMP's need to be installed along the road. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 3. Facing back north at same area of erosion shown in previous photo. Stormwater and sediment is directed toward the creek drainage and needs to be repaired and stabilized to prevent erosion. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 4. Further along the road is additional erosion on the road side that needs to be repaired and stabilized with BMP's. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 5. Facing south along the access road near the tank battery. There are List B noxious weeds along the is area of the road that need to be controlled. Red arrows points to Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 6. Facing southwest toward the tank battery. The fence around the tank is not maintained to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 7. There is oil stained soils at back side of tanks shown at red arrows. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023

Inspection Photos



Photo 8. Facing northeast toward the wellsite. There is vehicle rutting at the location which is not stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06124 | Date: 7/13/2023