

# Inspection Photos

Loc: 429093

Operator: AUSCO PETROLEUM INC

Inspection Date: 7/13/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 1.** Facing southwest toward the location. The blue frac tank does not have secondary containment and needs to be removed. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 2.** There are 2 orange buckets that appear to have oil with no labeling and no containment. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 3.** There is an unknown barrel with no labeling or containment. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 4.** Well sign is posted at wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 5.** Facing southwest toward the bitcoin equipment which is not in operation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 6.** There is a portable secondary containment installed for the 2 chemical totes.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 7.** The plastic liner has become folded over needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 8.** It appears in between the equipment there is darkened gravel from a possibly leak. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 9.** Northeast toward the bitcoin equipment. There are multiple tanks and secondary containment is not sufficient or maintained to contain a spill.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 10.** The plastic liner has become folded over needs to be repaired. There are water pump used to hold down the liner and should be removed if not need. Liner should be properly staked down.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 11.** South side of the location facing northeast. The old wattles in this area need to be replaced or removed. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 12.** Facing south at the perimeter ditch. The check dams have filled in with sediment and need to be cleaned out.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

## Inspection Photos



**Photo 13.** Facing northeast overlooking the location.



## Inspection Photos



**Photo 14** The wattles along the west perimeter of the location are degraded and need to be replaced or removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 429093 | Date: 7/13/2023

Inspection Photos



**Photo 15.** Facing south at the location.

