

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

07/14/2023

Document Number:

690204431

**FIELD INSPECTION FORM**Loc ID 429093 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	
Harkins, Liz		Lharkins@austineexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429093	LOCATION	AC			-	Pathfinder C 11-12 1	RI

**General Comment:**

On 7/13/2023, Ryan Costa conducted a follow up location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	There are some containers with no labeling. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 06/24/2023

**Emergency Contact Number:**

Comment:	There are several water pumps that do not appear to be in use and need to be removed. The frac tank remains unsued. The bitcoin equipment does not appear to be in use as well. All unused equipment and supplies not needed must be removed.		
Corrective Action:	Comply with 606.		Date: 06/24/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are degraded wattles at the south at west perimeter of the location that need to be replaced or removed. There are rock check dams at south side of the location that need maintenance. There are some buckets and barrels that need to be stored in containment. There is also an area of darkened gravel from a possible spill by the cooling units. The plastic liner at the cooling units has folded over and needs to be repaired. Previous corrective action was not completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)  
Implement or modify BMPs for improved material handling and spill prevention.

Date: 05/26/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204432	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6181650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6181650</a>