

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2023

Submitted Date:

07/14/2023

Document Number:

696305110

FIELD INSPECTION FORMLoc ID 422884 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422864	WELL	SI	03/01/2022	OW	123-33418	State Antelope 41-3HZ	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained Soil at Wellhead; see photos		
Corrective Action:	Handle waste in accordance with Rule 906 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.		Date: 07/28/2023
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Wellhead; see photos		
Corrective Action:	Comply with Rule 606		Date: 07/28/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused Master Valves at Wellhead; see photos		
Corrective Action:	Comply with Rule 606		Date: 07/28/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 422864 Type: WELL API Number: 123-33418 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

Routine Field Inspection. Unmarked Riser at Wellhead, unused Master Valves at Wellhead, Stained Soil at Wellhead.

petrie

07/14/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305111	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6181994