

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/16/2023

Document Number:

698600731**FIELD INSPECTION FORM**Loc ID 304899 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	
Quint, Craig		craig.quint@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275916	WELL	PR	01/01/2022	GW	125-09117	BLEDSE 15-7-3-43	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has erosion channel at well location. See Stormwater Section of report and Inspection Photo Log for additional details.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located inside stock panel fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Date: _____

Corrective Action: Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	2 Phase.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Motor has been removed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Chart in the meter box is dated 12-2-22.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel meter/seperator building.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	No motor for operation.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing valve closed. Currently no tubing connection, ball valve on top of stack.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	275916	Type:	WELL	API Number:	125-09117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well appears to be Shut In with wellhead casing valve closed. Gas meter chart is dated 12-2-22. Electronic well file reflects last reported production as 8/1/2022								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 413.							Date:	08/16/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Erosion channel has developed at well location and location entry section of access road. Sediment is flowing SE off location and down grade. Approximately 140 - 150 feet of channeling and 7 - 8 feet wide at widest point.</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.</p> <p>Date: 07/19/2023</p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600759	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182717