

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/16/2023

Document Number:

698600732**FIELD INSPECTION FORM**Loc ID 304938 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	
Quint, Craig		craig.quint@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276960	WELL	PR	03/01/2022	GW	125-09172	BLEDSE 8-18-3-43	PR

General Comment:Routine Inspection

Location				
Lease Road:				
Type	Access			
comment:	Two track road off maintained county road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Well sign located inside stock panel fencing.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on well sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Stock Panel Fencing.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Other	# 1			
Comment:	Meter/Separator Shed.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Marker are there but down.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Chart in meter box dated 12-2-22.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Casing valve closed. Currently no tubing connection, ball valve on top of stack.			

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Disconnected from well.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	276960	Type:	WELL	API Number:	125-09172	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well appears to be Shut In with wellhead casing valve closed. Gas meter chart is dated 12-2-22. Electronic well file reflects last reported production as 8/1/2022								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 413.							Date:	08/16/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600760	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182751