

Inspection Photos
Location Name: Bledsoe 13-17-3-43
Location ID: 125-02378



1. Well Sign located inside fencing.



2. View of Wellhead.

Inspection Photos
Location Name: Bledsoe 13-17-3-43
Location ID: 125-02378



3. View of Pump Jack. Note vegetation.




4. Motor removed from Pump Jack.

Inspection Photos
Location Name: Bledsoe 13-17-3-43
Location ID: 125-02378



5. View of Gas Meter Run and Vertical Separator inside shed.



6. Gas Meter Chart in Meter Box at time of inspection dated 12-2-22.

Inspection Photos
Location Name: Bledsoe 13-17-3-43
Location ID: 125-02378



7. Venting Regulator at wellhead.



8. Wider view of Wellhead and venting Regulator on right side of frame under red arrow.

Inspection Photos
Location Name: Bledsoe 13-17-3-43
Location ID: 125-02378



9. Erosion channel looking down slope to the NE from location.



10.0 Erosion channel looking SW towards location.