

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2023

Submitted Date:

07/17/2023

Document Number:

709400369

FIELD INSPECTION FORM

Loc ID 451045 Inspector Name: WOLD, REED On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
		mo.montoya@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457758	TANK BATTERY	AC			-	Dechant X01-07 battery	RI

General Comment:

This is an interim and stormwater inspection.

Upon arrival to site, a leaking crude oil tank inside secondary containment was observed leaking from a penile size hole approximately six inches from the bottom of the tank on the tank sidewall. The emergency contact number was called to report the spill, I was directed to a voicemail where a message was left describing the event. I was called back shortly after by a Noble representative indicating a response to the spill was underway.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: Unused equipment on site near well heads.

Corrective Action: 606.a Unused equipment

Date: 07/21/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 457758 Type: TANK API Number: - Status: AC Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Upon arrival to site, a leaking crude oil tank was observed leaking from a penile size hole approximately six inches from the bottom of the tank on the tank wall. The emergency contact number was called to report the spill, I was directed to a voicemail where a message was left describing the event. I was called back shortly after by a Noble representative indicating a response to the spill was underway.

Corrective Action: Comply with Rule 912.a.1.

Date: 07/13/2023

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400370	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6183379