

Inspection Photos

API: 043-05088

Operator: JAVERNICK OIL

Inspection Date: 7/13/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 1. Facing northeast along the access road. There is erosion occurring along the road that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 2. Facing northeast along the access road. BMP's along the road side are not maintained and have filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 3. Facing back southwest along the access road. Stormwater has eroded around the rock check dams. The straw bale is displaced and degraded.

There are noxious weeds (Field bindweed) along the road that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 4. View of Field bindweed which is a noxious weed that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 5. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023

Inspection Photos



Photo 6. It appears additional soil was brought into the erosion gully near the well however, this area is not stabilized. There are cracks along this area which indicate soil movement which needs to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-05088 | Date: 7/13/2023