

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 133-19 Pad

Location ID: 335369



Photo # 3305 From entrance to location



Photo # 3306 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 133-19 Pad

Location ID: 335369



Photo # 3308 Location



Photo # 3310 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 133-19 Pad

Location ID: 335369



Photo # 3312 Location



Photo # 3313 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 133-19 Pad

Location ID: 335369



Photo # 3315 Same unmarked deadman from a different view



Photo # 3321 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 133-19 Pad

Location ID: 335369



Photo # 3325 Tank label has incorrect capacity



Photo # 3326 Operator contact # partially illegible on RWF 331-19 wellhead sign