

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 27 yards from a drainage that contributes to the Colorado River.

Section/Township/Range: 19 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3168 Erosion & transport of sediment off location



Photo # 3169 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3194 Erosion & transport of sediment off location



Photo # 3195 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3191 Erosion & transport of sediment off location



Photo # 3192 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3188 Erosion & transport of sediment off location



Photo # 3172 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3173 Erosion & transport of sediment off location/sediment choking off vegetation (E/NE area of location)



Photo # 3184 Erosion & transport of sediment off location/sediment choking off vegetation (E/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3185 Erosion & transport of sediment off location/sediment choking off vegetation (E/NE area of location)



Photo # 3175 Erosion & transport of sediment off location/sediment choking off vegetation/Tunnel erosion going through berm (E/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3176 Tunnel erosion in berm (E/NE area of location)



Photo # 3177 Opposite side of berm – tunnel erosion has breached berm & is carrying sediment further offsite & into a drainage (E/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3181 Erosion & transport of sediment (E/NE area of location)



Photo # 3182 Tunnel erosion through another area of the berm (E/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3183 Tunnel erosion through berm (E/NE area of location)