

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Location Overview: Location is within High Priority/Density  
Habitat areas & drainages contribute to the Colorado River.**

**Section/Township/Range: 19 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3224 Lack of compaction/Stabilization**

**Photo # 3227 Lack of compaction/Stabilization**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3228 Lack of compaction/Stabilization**

**Photo # 3231 Lack of compaction/Stabilization**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3232 Lack of compaction/Stabilization**



**Photo # 3233 Lack of compaction/Stabilization**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3238 Lack of compaction/Stabilization**

**Photo # 3271 Lack of compaction/Stabilization**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3244 BMP's need maintenance (N/NW area of location)**



**Photo # 3246 BMP's being undercut by stormwater flow (N/NW area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3247 BMP's being undercut by stormwater flow (N/NW area of location)**

**Photo # 3248 BMP's being undercut by stormwater flow (N/NW area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3249 Tunnel erosion (N/NW area of pad)**

**Photo # 3251 Tunnel erosion (N/NW area of pad)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3253 Rill erosion (North side of location)**



**Photo # 3258 Rill erosion (North side of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3260 Rill erosion (North side of location)**



**Photo # 3267 Rill erosion (North side of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3276 Rill erosion (N/NE area of location)**



**Photo # 3277 Rill erosion (N/NE area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3301 BMP's being undercut by stormwater flow (south side of location)**

**Photo # 3281 Gulley erosion/insufficient BMP's (N/NE area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3282 Gully erosion/insufficient BMP's (N/NE area of location)**

**Photo # 3283 Gully erosion/insufficient BMP's (N/NE area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3286 Gully erosion/insufficient BMP's (N/NE area of location)**

**Photo # 3287 Tunnel erosion through berm allowing stormwater through leading to the gully erosion in previous 4 photos**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3288 Tunnel erosion through berm (N/NE area of location)**

**Photo # 3290 Tunnel erosion through berm (N/NE area of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3292 BMP's need maintenance/insufficient run on controls**

**Photo # 3293 BMP's need maintenance/insufficient run on controls**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3294 BMP's need maintenance/insufficient run on controls**

**Photo # 3295 BMP's need maintenance/insufficient run on controls**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3297 BMP's need maintenance**

**Photo # 3298 BMP's need maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 144-19 Pad**  
**Location #: 335109**



**Photo # 3242 Ditch needs maintenance**



**Photo # 3291 Ditch needs maintenance**