

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2023

Submitted Date:

07/19/2023

Document Number:

708300659**FIELD INSPECTION FORM**Loc ID 323962 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                              | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP        |       | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 211367      | WELL | PR     | 05/08/1997  | GW         | 045-07127 | UNOCAL GM 22-2  | PR          |
| 284087      | WELL | PR     | 05/01/2020  | GW         | 045-12079 | SOLVAY GM 423-2 | PR          |
| 284088      | WELL | PR     | 02/13/2007  | GW         | 045-12078 | SOLVAY GM 422-2 | PR          |

**General Comment:****COGCC Inspection Report Summary**

On 7/6/2023 at approximately 14:35, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SEW at Location ID #323962 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

This report was submitted 13 days after inspection due to technical issues. Any corrective actions will be effective from date of report submission, not date of inspection.

**Location**Overall Good: ☐

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Wellhead signs weathered but legible.   |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | TANK LABELS/PLACARDS  |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | OTHER   |       |  |
| Comment:             | Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | BATTERY   |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| <b>Fencing/:</b>   |                   |       |  |
| Type               | SEPARATOR         |       |  |
| Comment:           | Livestock fencing |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | TANK BATTERY      |       |  |
| Comment:           | Livestock fencing |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Livestock fencing |       |  |
| Corrective Action: |                   | Date: |  |

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| <b>Equipment:</b>     |     |       | corrective date |
| Type: Bird Protectors | # 4 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |

|                                   |  |  |       |
|-----------------------------------|--|--|-------|
| Type: Gas Meter Run               | # 5  |  |       |
| Comment:                          |  |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Horizontal Heated Separator | # 5  |  |       |
| Comment:                          |  |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Bradenhead                  | # 3  |  |       |
| Comment:                          | No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible. |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Plunger Lift                | # 3  |  |       |
| Comment:                          | All wells on plunger lift  |  |       |
| Corrective Action:                |  |  | Date: |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | 200 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |                        |                     |                     |             |       |
|--------------------|------------------------|---------------------|---------------------|-------------|-------|
| Type               | Capacity               | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate               | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           | Centalized containment |                     |                     |             |       |
| Corrective Action: |                        |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 211367 Type: WELL API Number: 045-07127 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 284087 Type: WELL API Number: 045-12079 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 284088 Type: WELL API Number: 045-12078 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Berms                   |                       |               |                          |         |

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 708300660    | Photo Log   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6188224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6188224</a> |