

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 310546

Inspection Document #: 701900943

SENW Section 11 T1N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Butterball B4-19
Location ID: 310546



Photo 1. 2022 aerial imagery of the well pad, access road, tank battery and reference area (north is up).

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing east. Note: bare ground in foreground of photos were caused by cattle grazing in the area and are not associated with oil and gas operations. Plant species in well pad disturbance appear consistent with reference area (see photo #5).

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 5. Reference area.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 6. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 7. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 8. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: lack of vegetation in background of east facing photo is caused by cattle grazing/disturbance and does not appear to be associated with oil and gas operations.

Inspection Photos
Location Name: Butterball B4-19
Location ID:310546



Photo 9. Left photo shows a pile of gravel in the eastern portion of the tank battery. Right photo shows tank battery access road that remains unreclaimed.