

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 330004

Inspection Document #: 701900949

SWSE Section 5 T3N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Becker 5-15
Location ID: 330004




Photo 1. 2022 aerial imagery of the well pad and associated tank battery (north is up).

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 2. Overview photo of the well pad taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo #4).

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 4. Well pad reference area.

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 5. Overview photo of the tank battery taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 6. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Becker 5-15
Location ID:330004



Photo 7. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: