

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322943

Inspection Document #: 701900951

SWSE Section 5 T3N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Becker 5-1
Location ID: 322943



Photo 1. 2022 aerial imagery of the well pad (north is up). Note: tank battery not pictured to the south is associated with the Becker 5-15 well API #123-18182.

Inspection Photos
Location Name: Becker 5-1
Location ID:322943



Photo 2. Overview photo of the well pad taken at ground level from the western edge facing northeast.

Inspection Photos
Location Name: Becker 5-1
Location ID:322943



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Becker 5-1
Location ID:322943



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: germination of desirable species observed at location. 80% vegetation cover has not yet been met, site will remain in-process until rule 1004 standards are achieved.

Inspection Photos
Location Name: Becker 5-1
Location ID:322943



Photo 5. Well pad reference area.