

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2023

Submitted Date:

07/20/2023

Document Number:

708901089

FIELD INSPECTION FORM

Loc ID 335069 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262717	WELL	PR	07/12/2002	GW	045-08049	CLOUGH RMV 160-22	PR
284637	WELL	PR	05/09/2006	GW	045-12248	CLOUGH RMV 225-22	PR
284639	WELL	PR	05/09/2006	GW	045-12247	CLOUGH RWF 423-22	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 07/20/2023 at approximately 09:58 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 160-22 pad. Location # 335069 in Garfield County Colorado.
Please refer to Inspection 708900301 conducted on 04/18/2023, previous corrective actions have been completed.
Location is within High Priority/Density Habitat areas & within close proximity to Bald Eagle Roost Site.
While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/split pad - Wellheads only, all production equipment associated with these 3 wells is located on the RMV 10-22 pad/production facility, location # 335175

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 3		corrective date
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Taylor plug located on RMV 160-22 bradenhead, bradenhead valve is accessible. No form of pressure monitoring equipment located on the other 2 wells bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>262717</u>	Type: <u>WELL</u>	API Number: <u>045-08049</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>284637</u>	Type: <u>WELL</u>	API Number: <u>045-12248</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>284639</u>	Type: <u>WELL</u>	API Number: <u>045-12247</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
		Compaction				
		Culverts				
Compaction						Small areas of light compaction
Gravel						Some areas of sparse gravel
		Check Dams				
		Retention Ponds				
Ditches						
		Gravel				Sparse
Check Dams						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Remote location/split pad - Wellheads only, all production equipment associated with these 3 wells is located on the RMV 10-22 pad/production facility, location # 335175	smelserw	07/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901090	Inspection 708901089 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189903
708901091	Inspection 708901089 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189904