

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2023

Submitted Date:

07/20/2023

Document Number:

708901095**FIELD INSPECTION FORM**Loc ID 335175 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211145	WELL	PR	02/15/1995	GW	045-06904	CLOUGH RMV-10-22	PR
281515	WELL	PR	08/01/2006	GW	045-11477	CLOUGH RWF 322-22	PR
281517	WELL	PR	07/30/2006	GW	045-11478	CLOUGH RWF 422-22	PR
281518	WELL	PR	07/30/2006	GW	045-11479	CLOUGH RWF 522-22	PR
281521	WELL	PR	07/30/2006	GW	045-11480	CLOUGH RWF 32-22	PR

General Comment:**CECMC Inspection Report Summary**

On 07/20/2023 at approximately 10:09 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 10-22 pad.

Location # 335175 in Garfield County Colorado.

Please refer to Inspection 708900302 conducted on 04/18/2023, previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas & within close proximity to Bald Eagle Roost Site.

While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/remote location - 3 wells associated with this pad are located on the RMV 160-22 pad, location # 335069

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Deadman # & Marked	# 5			
Comment:	Marked			
Corrective Action:				Date:
Type: Plunger Lift	# 5			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 5			
Comment:	RMV 10-22 & RWF 522-22 wells have Taylor plugs on bradenhead, bradenhead valves are accessible. No form of pressure monitoring equipment located on the other 3 wells bradenheads. All bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Gas Meter Run	# 8			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 6			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient		
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:	Separate containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,

Comment:	Centralized containment
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211145	Type:	WELL	API Number:	045-06904	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281515	Type:	WELL	API Number:	045-11477	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281517	Type:	WELL	API Number:	045-11478	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281518	Type:	WELL	API Number:	045-11479	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281521	Type:	WELL	API Number:	045-11480	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
Compaction						Small areas of light compaction
		Gravel				Sparse
		Culverts				
		Retention Ponds				
Check Dams						
Berms						
Sediment Traps						
		Ditches				
		Compaction				
		Check Dams				
Ditches						
Gravel						
		Rip Rap				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Split pad/remote location - 3 wells associated with this pad are located on the RMV 160-22 pad, location # 335069	smelserw	07/20/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901096	Inspection 708901095 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190168
708901097	Inspection 708901095 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190169