



**Inspected Facilities**

Facility ID: 275236 Type: WELL API Number: 045-13492 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Sales Line	1 of Lines
----	------------------	------------

Flowline Description

Flowline Type: Sales Line Size: 2" Material: Carbon Steel  
 Variance: Age: New Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Test on new sells line to replace failed/leaking line discovered by COGCC now ECMC staff. 2.375" carbon pipe from well to separator. Line not filled prior to testing on high heat day with line of cool water. Continious increase in pressure being bleded at appox. 1360psi and try to maintain 1250 psi. No leaks noticed during test or at end of test.

Corrective Action: Fill lines in advance of testing to minimize fluctuation in pressures.

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103777	Flowline integrity inspection 701103776 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190749">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190749</a>