

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/14/2023

Submitted Date:

07/20/2023

Document Number:

701103778

**FIELD INSPECTION FORM**

Loc ID 322495 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10770  
Name of Operator: VISION ENERGY LLC  
Address: P O BOX 370  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
O'Hare, Mollie		mco@visionenergy.biz	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210630	WELL	TA	07/01/2021	GW	045-06386	CALF CANYON-FEDERAL 26-1	EG

**General Comment:**

[Flowline integrity inspection](#)

**Inspected Facilities**

Facility ID: 210630 Type: WELL API Number: 045-06386 Status: TA Insp. Status: EG

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT dated 12/19/2020 Form 21 doc 402569803

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type:	2 of Lines
----	-------	------------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: 2-2" lines open end running from well to across roadway.

Corrective Action: Abandon or cap and tag lines. Date: 08/23/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103779	Flowline integrity inspection 701103778 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190750">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190750</a>