

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SESW

Location ID: 324142

Date: 7/10/2023



West Entrance to Location – Photo #05109



East Side of Location – Photo #05110

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SESW

Location ID: 324142

Date: 7/10/2023



Wellhead – Photo #05111



Separators – Photo #05116

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SESW

Location ID: 324142

Date: 7/10/2023



Tank Battery – Photo #05117



Rill Erosion Causing Run-On to Location – Photo #05113

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SESW

Location ID: 324142

Date: 7/10/2023



Rill Erosion Causing Run-On to Location – Photo #05114