

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/16/2023

Document Number:

698600731**FIELD INSPECTION FORM**Loc ID 304899 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	
, Engineering		dnr_cogccengineering@state.co.us	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275916	WELL	PR	01/01/2022	GW	125-09117	BLED SOE 15-7-3-43	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road. Two track has erosion channel at well location. See Stormwater Section of report and Inspection Photo Log for additional details.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign located inside stock panel fencing.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on well sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 0		
Comment:	Motor has been removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel meter/seperator building.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	No motor for operation.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Wellhead. Casing valve closed. Currently no tubing connection, ball valve on top of stack.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Chart in the meter box is dated 12-2-22.			
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:	2 Phase.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	275916	Type:	WELL	API Number:	125-09117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well appears to be Shut In with wellhead casing valve closed. Gas meter chart is dated 12-2-22. Electronic well file reflects last reported production as 8/1/2022								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 413.							Date:	08/16/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Erosion channel has developed at well location and location entry section of access road. Sediment is flowing SE off location and down grade. Approximately 140 - 150 feet of channeling and 7 - 8 feet wide at widest point.</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.</p> <p>Date: 07/19/2023</p>						
<p><b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403465601	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182720">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182720</a>
698600759	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182717</a>