

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2023

Submitted Date:

07/23/2023

Document Number:

698600772

FIELD INSPECTION FORM

 Loc ID 313996 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10699
 Name of Operator: OWN RESOURCES OPERATING LLC
 Address: 38 PALMER CREST CT
 City: SPRING State: TX Zip: 77381
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227548	WELL	PR	04/01/2022	GW	095-06012	FERGUSON 1-26	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Located on Meter Shed at well site.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contactr information posted on Meter Shed door below well sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel post and pole barrier protection at wellhead.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Chart in meter box dated 7-3-23. Valves are open.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Gas dryer vessel between wellhead and gas meter run.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Well appears to be producing out of production casing string. Valve is open.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Steel Meter Shed.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 227548 Type: WELL API Number: 095-06012 Status: PR Insp. Status: PR

Producing Well

Comment: Well appears to be producing out of production casing string. Casing valve is open and valves at gas meter run are open.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600790	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6192036