

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/24/2023

Document Number:

708200394

**FIELD INSPECTION FORM**Loc ID 327020 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email   | Comment |
|---------------|-------|---|---------|
| ,             |       | rbucogccinspectionreports@chevron.onmicrosoft.com |         |
| ZUNIGA, ERICA |       | ericazuniga@chevron.com                           |         |

**Inspected Facilities:**

| Facility ID | Type                        | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|-----------------------------|--------|-------------|------------|-----------|----------------------------|-------------|
| 150392      | UIC<br>ENHANCED<br>RECOVERY | CL     |             |            | -         | LILLI FIELD UNIT           | RI          |
| 246220      | WELL                        | PA     | 01/16/2020  | ERIW       | 123-14017 | LILLI UNIT 6-3             | RI          |
| 327020      | LOCATION                    | CL     |             |            | -         | LILLI UNIT-68N58W<br>3SENW | RI          |

**General Comment:**

This is a Final Reclamation Inspection for PA Well API#123-14017 and its associated tank battery. Well was plugged and abandoned 01/16/2020.

| Inspected Facilities |               |       |                 |             |                  |         |           |               |           |
|----------------------|---------------|-------|-----------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>150392</u> | Type: | <u>UIC</u>      | API Number: | <u>-</u>         | Status: | <u>CL</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |                 |             |                  |         |           |               |           |
| Facility ID:         | <u>246220</u> | Type: | <u>WELL</u>     | API Number: | <u>123-14017</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |                 |             |                  |         |           |               |           |
| Facility ID:         | <u>327020</u> | Type: | <u>LOCATION</u> | API Number: | <u>-</u>         | Status: | <u>CL</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |                 |             |                  |         |           |               |           |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

|   |   |  |                       |               |                          |                        |
|---|---|--|-----------------------|---------------|--------------------------|------------------------|
|   | This location does not comply with Rule 1004. During this inspection, Staff observed that the location appears to have been reclaimed with evidence of desirable perennial vegetation. However, the former access road and portions of the well location also had evidence of undesirable plant species (e.g. russian thistle, downy brome, and CO List C Noxious weed-field bindweed) and areas of bare/exposed soils. It does not appear the undesirable vegetation was managed for and the plants have seeded out. Additional reclamation activities are required in order to meet Rule 1004 Standards. Refer to attached inspection photos. |  |                       |               |                          |                        |
| Corrective Action:  | Comply with Rule 1004. Corrective action date is the date the location was observed out of compliance.  |  |                       |               |                          | Date <b>07/19/2023</b> |
| Overall Final Reclamation <span style="color: red;">Fail</span> Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |   |  |                       |               |                          |                        |
| <b>Storm Water:</b>   |   |  |                       |               |                          |                        |
| Loc Erosion BMPs  | BMP Maintenance   | Lease Road Erosion BMPs  | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                |
|   |   |  |                       |               |                          |                        |
| Comment:  |   | At the time of this inspection, no stormwater erosion issues were observed at location or along the access road. |                       |               |                          |                        |
| Corrective Action:  |   |  |                       |               |                          | Date:                  |
| <b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT   |   |  |                       |               |                          |                        |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 708200401    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6193472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6193472</a> |