

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2023

Submitted Date:

07/25/2023

Document Number:

698600776

### FIELD INSPECTION FORM

Loc ID 303993 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING State: TX Zip: 77381

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253893	WELL	PR	10/21/2005	GW	125-07771	BROWN 44-33R	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Located at well site fencing.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Emergency contact information posted on well sign.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Stock panel fencing around surface equipment at well site.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Meter Shed.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Digital Gas Meter Run.		
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Knock Out Vessel.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack power and control panel.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 253893 Type: WELL API Number: 125-07771 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Tubing valve open. Casing valve open. Meter run valves open.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600806	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6194576">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6194576</a>