


Inspection Photos
Location Name: Garrett 15-33-6-45
API Number: 095-06120



1. Well sign. Emergency contact number is disconnected.



2. View of wellhead. Note soil staining around base of wellhead. Note T Post left at site.

Inspection Photos
Location Name: Garrett 15-33-6-45
API Number: 095-06120



3. Water that has collected around base of wellhead with oily sheen.




4. Concrete pad with lube oil staining and chunks as identified in pervious inspection still present. Note debris and trash inside fencing.

Inspection Photos
Location Name: Garrett 15-33-6-45
API Number: 095-06120



5. View of gas meter run inside meter shed.



6. Meter calibration test report dated 7-14-20.

Inspection Photos
Location Name: Garrett 15-33-6-45
API Number: 095-06120



7. Meter chart in meter box at time of inspection dated 12-1-22.



8. Additional view inside well site fencing. Stained soils, production related debris, concrete pad.

Inspection Photos
Location Name: Garrett 15-33-6-45
API Number: 095-06120



9. Oily staining inside well fencing.



10. One of the four anchors located that require additional marking to comply with rule.