

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 7/11/2023



SW Corner of Location – Photo #05143



NW Corner of Location – Photo #05144

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 7/11/2023



NE Corner of Location – Photo #05145



SE Corner of Location – Photo #05146

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 7/11/2023



Separator – Photo #05150



Tank Battery – Photo #05151

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 7/11/2023



Rill Erosion Transporting Sediment Onto Location – Photo #05149



Check Dam Needs Maintenance – Photo #05147

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSW

Location ID: 324088

Date: 7/11/2023



Location Lacks Stabilization – Photo #05153



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05154**