

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/42-11 Frac Pad

Location ID: 334956

Date: 7/11/2023



NW Corner of Location – Photo #05180



SW Corner of Location – Photo #05181

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/42-11 Frac Pad

Location ID: 334956

Date: 7/11/2023



SE Corner of Location – Photo #05182



NE Corner of Location – Photo #05185

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/42-11 Frac Pad

Location ID: 334956

Date: 7/11/2023



Wellheads – Photo #05186



Separators – Photo #05189

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/42-11 Frac Pad

Location ID: 334956

Date: 7/11/2023



Jul 11, 2023 at 10:39:58
Parachute CO 81635
United States



Jul 11, 2023 at 10:38:24
Parachute CO 81635
United States

Tank Battery – Photo #05190

Unprotected Stockpile – Photo #05183

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/42-11 Frac Pad

Location ID: 334956

Date: 7/11/2023



**Inadequate Erosion Control of Location Surface – Photo
#05184**