

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/26/2023

Document Number:

698600785

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 304867 _____ St John, William (Cal) _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 66190 _____
 Name of Operator: OMIMEX PETROLEUM INC _____
 Address: 2501 HARWOOD ST STE 1238 _____
 City: _____ DALLAS _____ State: _____ TX _____ Zip: _____ 75201 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 _____ Number of Comments
 4 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Quint, Craig		craig.quint@state.co.us	
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275658	WELL	PR	05/01/2021	GW	125-09083	BLEDSOE 1-25-3-44	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Located inside fencing at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information is posted on well sign. The numbering is peeling off due to weathering and needs to be replaced as it is close to unreadable.		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growing inside fencing around surface equipment.		
Corrective Action:	Comply with Rule 606.		Date: 08/03/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Stock panel fencing around surface equipment at well site.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Steel Meter Shed.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve closed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Cement slab under Pump Jack.		

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter not calibrated annually. Test report attached to gas meter run is dated 99-11-20. Chart in meter box at time of inspection is dated 12-2-22. Meter run valves are open.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	08/28/2023
Type: Pump Jack	# 1		
Comment:	Motor removed.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 275658 Type: WELL API Number: 125-09083 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve closed. Valves at gas meter run are open. At time of inspection the well was SI based on valve settings. Review of electronic well production file reflects last production reporting 8/1/2022 and well was reported as PR at that time. Operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 08/28/2023

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At time of inspection several erosion channels were noted that start on location and flow SW off location ending in large sediment plume at bottom of slope. The larger channel starts along the S side of the stock panel fencing flows down grade approximately 140' and is 20' wide with a dpth greater than 3' in several places. Sediment plume at bottom of slope is approximately 17' X 12'.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 07/31/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403477265	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195708
698600785	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195395
698600810	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195315