

TEP
PA 541-34
Location ID:
335378



Well heads



Tank battery

TEP
PA 541-34
Location ID:
335378



Separators and lack of calibration card access



Ditch on side of location lacks erosion control

TEP
PA 541-34
Location ID:
335378



Cut slope lacks stabilization and migrating onto location encroaching on production equipment



Cut slope lacks stabilization and migrating onto location encroaching on production equipment

TEP
PA 541-34
Location ID:
335378



Cut slope lacks stabilization and migrating onto location encroaching on production equipment



Cut slope lacks stabilization and migrating onto location encroaching on production equipment

TEP
PA 541-34
Location ID:
335378



Cut slope lacks stabilization and migrating onto location encroaching on production equipment



Sediment migrated over skid of production equipment

TEP
PA 541-34
Location ID:
335378



Cut slope lacks stabilization and migrating onto location encroaching on production equipment



Cut slope lacks stabilization and migrating onto location encroaching on production equipment