

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Lease road entrance sign



Energy & Carbon Management Commission  
40.48238, -104.85246, 1474.4m, 121°  
07/27/2023 11:43:21

Production facility

**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



Energy & Carbon Management Commission  
40.48138, -104.85228, 1456.0m, 126°  
07/27/2023 11:59:20

**Debris**



Energy & Carbon Management Commission  
40.48136, -104.85219, 1457.1m, 116°  
07/27/2023 11:59:38

**Debris**

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Debris



Debris

**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Unused equipment**