

**Inspection Photos**  
**Location Name: Washburn GX15-62Hn**  
**Location ID: 428699**



**Photo 1 – Pumping Unit**



**Photo 2 – Gas Engine**

**Inspection Photos**  
**Location Name: Washburn GX15-62Hn**  
**Location ID: 428699**



**Photo 3 – Wellhead**



**Photo 4 – Riser has been Locked Out**

**Inspection Photos**  
**Location Name: Washburn GX15-62Hn**  
**Location ID: 428699**



**Photo 5 – Weeds REMAIN at ECD**



**Photo 6 – Weeds and Tumbleweed Debris East of Separators and ECD Overhead Line**

**Inspection Photos**  
**Location Name: Washburn GX15-62Hn**  
**Location ID: 428699**



**Photo 7 – Tumbleweed Debris at South Separator**



**Photo 8 – Weeds have been mowed**

Inspection Photos  
Location Name: Washburn GX15-62Hn  
Location ID: 428699



Photo 9 – Capacity Label now Adequate



Photo 8 – Tank Battery Sign

Inspection Photos  
Location Name: Washburn GX15-62Hn  
Location ID: 428699



Photo 11 – Weeds mowed down



Photo 12 – Weeds mowed down – Some REMAIN East of Overhead Line

**Inspection Photos**  
**Location Name: Washburn GX15-62Hn**  
**Location ID: 428699**



**Photo 13 – Tank Battery – Tumbleweed Debris has been removed**