

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2023

Submitted Date:

07/28/2023

Document Number:

705000374**FIELD INSPECTION FORM**Loc ID 305367 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276895	WELL	SI	01/01/2021	OW	123-22861	BETZ 30-11	PA
446124	TANK BATTERY	AC	07/27/2006		-	BETZ-65N67W 30NENE	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 276895 Type: WELL API Number: 123-22861 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Betz 30-11) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403368884 received 04/10/2023. OL WH flowline removal work has not been completed; flowline riser observed at WH excavation. Fenced excavation also observed at facility/ battery area; flowline risers (isolated) were observed. Facility/ battery decommissioning work is in progress (tanks moved/ berms removed). On location dump and process flowline removal work at facility/ battery is pending. Excavation/ remediation work (per form 27) is in progress.

Corrective Action:

Date:

Facility ID: 446124 Type: TANK API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000378	Signage at PA well; flowline riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198553
705000379	Flowline risers at facility; bull plugged (OOS GMR)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198554